



®

YESHIVA UNIVERSITY

Annual Fire Safety Report

October 1, 2024

Wilf Campus

Washington Heights section of Manhattan

Annual Fire Safety Report

2022

Name of Residence	Fires and Cause	Injuries	Deaths	Value of Damages
Rubin Hall	0	0	0	0
Morgenstern Hall	0	0	0	0
Muss Hall	0	0	0	0
Strenger Hall	0	0	0	0

Independent Housing Program (IHP)

Address of Residence	Fires and Cause	Injuries	Deaths	Value of Damages
475 West 186th St.	0	0	0	0
90 Laurel Hill Terrace	0	0	0	0
501 West 184th St.	0	0	0	0
2498 Amsterdam Ave.	0	0	0	0
403 Audubon Avenue	0	0	0	0
521 West 185th St.	0	0	0	0
551 West 185th St.	0	0	0	0
556 West 185th St.	0	0	0	0
407 Audubon Avenue	0	0	0	0
497 West 182 nd St.	0	0	0	0
24 Laurel Hill Terrace	0	0	0	0
36 Laurel Hill Terrace	0	0	0	0
480 West 187th St.	0	0	0	0
495 West 187th St.	0	0	0	0
490 West 187 th St.	0	0	0	0
142 Laurel Hill Terrace	0	0	0	0

2021

Name of Residence	Fires and Cause	Injuries	Deaths	Value of Damages
Rubin Hall	0	0	0	0
Morgenstern Hall	0	0	0	0
Muss Hall*	1	0	0	\$350.00
Strenger Hall	0	0	0	0

Independent Housing Program (IHP)

Address of Residence	Fires and Cause	Injuries	Deaths	Value of Damages
475 West 186th St.	0	0	0	0
90 Laurel Hill Terrace	0	0	0	0
501 West 184th St.	0	0	0	0
2498 Amsterdam Ave.	0	0	0	0
403 Audubon Avenue	0	0	0	0
521 West 185th St.	0	0	0	0
551 West 185th St.	0	0	0	0
556 West 185th St.	0	0	0	0
407 Audubon Avenue	0	0	0	0
497 West 182 nd St.	0	0	0	0
24 Laurel Hill Terrace	0	0	0	0
36 Laurel Hill Terrace	0	0	0	0
480 West 187th St.	0	0	0	0
485 West 187th St.	0	0	0	0

- “Cause of Fire”: The factor or factors that give rise to a fire, including intentional action, unintentional, mechanical failure, or an act of nature.
- “Fire- related injury” : Any instance in which a person is injured as a result of fire. This included injuries sustained from natural or accidental causes and injuries sustained while involved in fire control attempting a rescue or escaping from a fire.
- “Fire- related death” : Any instance in which a person is killed as a result of a fire or dies within one year of injuries sustained as a result of a fire.
- “Value of property damage” : The estimated value of the loss of the structure and its contents, including contents damaged Suc.001 Tc t0.tr in 002 Tc (c)36n 06.n 0024o3lu50 To

The University, at times, also houses students in the following apartment buildings (IHP).

Address of Residence	Sprinkler/Fire Suppression	Detection Type	Reduction Mechanisms	Fire Alert
475 West 186th St.	None	Smoke Detectors	None	None
90 Laurel Hill Terrace	*Partial Sprinkler	Smoke Detectors	None	None
501 West 184th St.	None	Smoke Detectors	None	None
2498 Amsterdam Ave.	None	Smoke Detectors	None	None
403 Audubon Avenue	None	Smoke Detectors	None	None
521 West 185th St.	None	Smoke Detectors	None	None
551 West 185th St.	None	Smoke Detectors	None	None
556 West 185th St.	None	Smoke Detectors	None	None
407 Audubon Avenue	None	Smoke Detectors	None	None
497 West 182 nd St.	None	Smoke Detectors	None	None
24 Laurel Hill Terrace	None	Smoke Detectors	None	None
36 Laurel Hill Terrace	None	Smoke Detectors	None	None
480 West 187th St.	None	Smoke Detectors	None	None
495 West 187th St.	None	Smoke Detectors	None	None
490 West 187 th St.	None	Smoke Detectors	None	None

9 0.4814 Tc98 00.W n1.9450a1801536f445.482r08r(s)79.4 (t)207.987098398.46 T04815109 a f02397039804661488 T8100.1r f0297.783

Portable Electrical Appliances, Smoking, and Open Flames in a H

Daily Fire Log

As required by federal law, each University campus maintains an easily understood written Daily Fire Log. The main office of the Wilf Campus Security Department, located on the Wilf Campus at 2521 Amsterdam Avenue (1st Floor), maintains the Fire Log for the Wilf Campus

The Daily Fire Log lists the following information for each fire that occurs in on-campus student housing: The date the fire occurred, time of occurrence, general location and nature of fire.

The Chief of Security ensures that entries are made in the Fire Log within two business days after the Security Department receives a report of a fire and updates those entries within two business days anytime it receives additional information about the fire. The

asFld [(tilw 0. Tw 0.)1 (Am)M (irc)3 (cn(eiv)6 (es)24 (s)7r08 Tw 0.3l)3 (()5. (s)7)4 (atJ 0.27(eiv)6 (es